

# NOTICE:

For oil pan #11-900, #11-910, #11-920.

When using Canton pickup tubes WITHOUT the use of our main support, a 1/4" spacer is required on the pickup mounting main cap stud. Without the spacer the pickup will not be at the correct height.